

January 27, 2022

2021 Annual Compliance Audit

Water System:	Code:	
HEADINGLEY REGIONAL - PWS	89.40	
Water System Owner:	Address:	
Cartier Regional Water Co-op, Inc.	6000 Portage Avenue, Headingley, MB R4H 1E8	
Operating Licence:	Expiry Date:	
PWS-16-591	November 30, 2021	
Water System Assessment Due Date:		
March 1, 2026		
Public Water System Annual Report Due Date:	Advisory Notification Plan Due Date:	
March 31, 2022	May 1, 2022	

- 1) This report documents compliance of the Headingley Regional Public Water System for the period from January 1 to December 31, 2021.
- 2) This report provides specific information on the non-compliance incidents identified in the summary below.
- 3) Other than the information provided in this report, the water supplier has complied with The Drinking Water Safety Act, its supporting regulations, and the terms and conditions of the water system's current operating licence.
- 4) This report is based on information submitted by the water supplier, agents of the water supplier, and / or the Province of Manitoba.
- 5) Where non-compliance items are identified, the issues do not necessarily translate into increased public health risk. The Office of Drinking Water uses processes, including boil water advisories, to notify water users of a public health risk.

Non-compliance with Treatment Standards:

Water system was compliant in the audited time period.

Non-compliance Incidents:

Date	Incident	Outcome
January	Failure to take and/or record turbidity at the same time and location(s) as bacteriological distribution system sampling	Non-compliant
February	Failure to take and/or record turbidity at the same time and location(s) as bacteriological distribution system sampling	Non-compliant
March	Failure to take and/or record turbidity at the same time and location(s) as bacteriological distribution system sampling	Non-compliant
April	Failure to take and/or record turbidity at the same time and location(s) as bacteriological distribution system sampling	Non-compliant
May	Failure to take and/or record turbidity at the same time and location(s) as bacteriological distribution system sampling	Non-compliant
June	Failure to take and/or record turbidity at the same time and location(s) as bacteriological distribution system sampling	Non-compliant
July	Failure to take and/or record turbidity at the same time and location(s) as bacteriological distribution system sampling	Non-compliant
August	Failure to take and/or record turbidity at the same time and location(s) as bacteriological distribution system sampling	Non-compliant
September	Failure to take and/or record turbidity at the same time and location(s) as bacteriological distribution system sampling	Non-compliant
October	Failure to take and/or record turbidity at the same time and location(s) as bacteriological distribution system sampling	Non-compliant
November	Failure to take and/or record turbidity at the same time and location(s) as bacteriological distribution system sampling	Non-compliant
December	Failure to take and/or record turbidity at the same time and location(s) as bacteriological distribution system sampling	Non-compliant

2021 Annual Compliance Audit HEADINGLEY REGIONAL - PWS January 1, 2021 to December 31, 2021

If you have any questions, please do not hesitate to contact me at (204) 794-3904.

Sincerely,

Marc Balcaen Supervisor, Drinking Water Officer